

ADDENDUM #2

Request For Bids – Bridge Maintenance Projects

Question: Can you confirm the “HMA Surface, Rem” and “HMA, 4EL” quantities at each bridge. It appears to me that the Membrane numbers seem reasonably close, but the designer appears to have converted from SFT to SYD incorrectly for the removal item, which then also translated to over exaggerated HMA quantities. Otherwise, if you believe those quantities are accurate, can you clarify where the additional work will occur?

Response: The numbers in removal/paving quantities are correct. We are planning on the approaches needing to be removed and repaved to provide a smooth transition to the resurfaced bridge.